



CERTSWARRIOR

API

API-571
Corrosion and Materials Professional

Questions & Answers PDF

For More Information:
<https://www.certswarrior.com/>

Features:

- 90 Days Free Updates
- 30 Days Money Back Guarantee
- Instant Download Once Purchased
- 24/7 Online Chat Support
- Its Latest Version

Latest Version: 8.0

Question: 1

_____ is a change in the microstructure of certain carbon steels and 0.5 Mo steels after long term operation in the 800° F to 1100° F range.

- A. Graphitization
- B. Softening
- C. Temper Embrittlement
- D. Creep

Answer: A

Question: 2

What structure is 304 stainless steel?

- A. Martensitic
- B. Austenitic
- C. Duplex
- D. Ferritic

Answer: B

Question: 3

_____ is the result of cyclic stress caused by variations in temperature.

- A. Creep
- B. Thermal Fatigue
- C. Cyclic Cracking
- D. Stress Corrosion Cracking

Answer: B

Question: 4

General or localized corrosion of carbon steels and other metals caused by dissolved salts, gases, organic compounds or microbiological activities is called _____.

- A. Flue Gas Corrosion
- B. Atmospheric Corrosion
- C. Cooling Water Corrosion
- D. None of the Above
- E. All of the Above

Answer: C

Question: 5

What structure is 410 stainless steel?

- A. Martensitic
- B. Austenitic
- C. Duplex
- D. Ferritic

Answer: A

Question: 6

The sudden rapid fracture under stress (residual or applied) where the material exhibits little or no evidence of ductility or plastic deformation is called _____.

- A. 885° F Embrittlement
- B. Temper Embrittlement
- C. Stress Corrosion Cracking
- D. Brittle Fracture

Answer: D

Question: 7

What structure is 409 stainless steel?

- A. Martensitic
- B. Austenitic
- C. Duplex
- D. Ferritic

Answer: D

Question: 8

Low alloy steels contain a maximum of _____ chrome.

- A. 5%
- B. 6%
- C. 7.5%
- D. 9%

Answer: D

Question: 9

Which of the following can be affected by 885° F Embrittlement?

- A. 410 SS
- B. 430 SS
- C. 308 SS
- D. Alloy 2205
- E. A, B and D

Answer: E

Question: 10

For 5Cr-0.5Mo, what is the threshold temperature for creep?

- A. 500° F
- B. 800° F
- C. 600° F
- D. 700° F

Answer: B

Question: 11

_____ has been a major problem on coke drum shells.

- A. Thermal fatigue
- B. Stress cracking
- C. Erosion
- D. Temper embrittlement

Answer: A

Question: 12

Thermal fatigue cracks propagate _____ to the stress and are usually dagger shaped, transgranular and oxide-filled.

- A. Axial
- B. Diagonal
- C. Transverse
- D. Angular

Answer: C

Question: 13

Inspection for wet H₂S damage generally focuses on _____ and _____.

- A. Weld seams
- B. Nozzles
- C. Trays
- D. Down comers
- E. A and B

Answer: E

Question: 14

_____ is a form of erosion caused by the formation and instantaneous collapse of innumerable tiny vapor bubbles.

- A. Condensate corrosion
- B. Cavitation
- C. Dew-Point corrosion
- D. Atmospheric corrosion

Answer: B

Question: 15

With CUI, corrosion rates _____ with increasing metal temperatures up to the point where the water evaporates quickly.

- A. Decrease
- B. Increase
- C. Stay the same
- D. None of the above

Answer: B



CERTSWARRIOR

FULL PRODUCT INCLUDES:

Money Back Guarantee



Instant Download after Purchase



90 Days Free Updates



PDF Format Digital Download



24/7 Live Chat Support



Latest Syllabus Updates



For More Information – Visit link below:

<https://www.certswarrior.com>

16 USD Discount Coupon Code: U89DY2AQ